Appendix A

Agency

Institutional Controls Field Inspection Checklists and Minutes from Kick-off and Close-out Meetings

NSPECTOR	: KATHY IVY Name	Organization	WAS-3 MANAGER Title
NSPECTOR	: Marge Facu	usH 10€0	WAG-3 MANAGER
•	Name	Organization	Title
l. Group Ni	umber or NFA Design	nation:l	
		ation:lat would limit or control pub	lic trespass:
2. Identify s	security restrictions th	,	lic trespass:
2. Identify s	security restrictions thRestricted Security	at would limit or control pub	•

4. Release Site IDs, descriptions, and visual inspection matrix. On the table below please indicate "YES" or "NO" for observations based upon the visual inspection. If actions have been taken associated with remediation, site changes, or changes in land-use, take photographs and fill out the "Site Inspection Photo Number Log" for the annual report. Sign location specifications are provided in the ICP. Deficiencies should be addressed in No. 7.

Release Site	Description	Status of Remedial Action	Evidence of Human Intrusion	Observed Boundary Monuments	Observed Warning Signs/Barriers
CPP-15	Solvent burner E. of CPP-605	Pre-Design	Yes	Marker ON NE	Yes
CPP-16	Contaminated soil from leak in line from CPP WM-181 to PEW Evaporator	Pre-Design			
CPP-20	CPP-604 Radioactive Waste Handling Area	Pre-Design			- un
CPP-24	CPP Tank Farm Area bucket spill	Pre-Design			
CPP-25	Contaminated soil in the Tank Farm area N of CPP-604	Pre-Design			
CPP-27	Contaminated soil in the Tank Farm Area E of CPP-604	Pre-Design			
CPP-28	Contaminated soil in Tank Farm Area S of WM-181 near VB A-6	Pre-Design			
CPP-30	Contaminated soil in the Tank Farm Area near valve box B-9	Pre-Design			
CPP-31	Contaminated soil in Tank Farm Area S of tank WM-183	Pre-Design			

CPP-26

	Release Site	Description	Status of Remedial Action	Evidence of Human Intrusion	Observed Boundary Monuments	Observed Warning Signs/Barriers
	CPP-32	Contaminated soils in Tank Farm Area SW & NW of VB B-4	Pre-Design			
	CPP-33	Contaminated soils in Tank Farm Area near WL-102 NE of CPP-604	Pre-Design			
*	CPP-58	CPP PEW Evaporator overhead pipe spills	Pre-Design	Yes-##	Yes-Partal	Yes-partral
	CPP-79	Tank Farm release near VB A-2	Pre-Design			
	CPP-96	Tank Farm Interstitial Soils	Pre-Design		XXX	sign at TF so

** Group I draining upgrade construction out through this site

xxx - use were toll that corners of TF Fonce have been surveyed, but no markers exist

Institutional Controls records review. On the table below, please indicate "YES", "NO", a"NA" observed

That for records reviewed during the inspection. Answers of "NA" indicate that the records, such as

release site not accessed for work purposes).

5.

work permits or personnel training records, were not applicable at the time of the inspection (i.e.,

SEE	ITEM 7	B		· · · · · · · · · · · · · · · · · · ·	,	
	CFLUP	Review		Observed		Observed
Release Site	Observed Surveyed Maps	Listing of Required ICs	Observed Work Permit(s)/RWPs	Personnel Training Records	Observed NOD(s)	Notices to Affected Stakeholders
CPP-15		<u> </u>	N/A	soe item	N/A	
CPP-16			<u> </u>	8(0)		
CPP-20						
CPP-24						
CPP-25						
CPP-26						
CPP-27						
CPP-28						
CPP-30						
CPP-31						·
CPP-32						
CPP-33						
CPP-58						
CPP-79						
CPP-96				V		

Could not inspect signage along bldg due to on-going group 1 R.A. Construction

Standard 101 Work Permits	Radiological Work Permits	Notices of Disturbance
inspection year	-	
·	<u> </u>	
EFICIENCIES:		·
n., 11, . 4,	tanatan da	Lana Lana amandii La 4-7 4
	iencies and what efforts or measures	nave been of will be taken to
correct problems:		
A) ALL CPP 26 to 1	st of sites included in	TF.
	tion on checklist res	
designation	outside the fee	σ_{-}
11211		
B) Since the CI	Flue is aurrently being	underted we
		7
could not cha	it those items sent	desire to this
		during to this
	Cie, Observed Survey m s and Observed Dotte	are (isting of b) stakeholder
record review	Cip., Observed Survey m	desing to this are (isting of b stave holder)
record review	Cip., Observed Survey m	desing to this are (isting of Stavotoffles)
record review	Cip., Observed Survey m	are , (isting of
record review	Cip., Observed Survey m	are (isting of
record review	Cip., Observed Survey m	are (isting of Stavarolles)
record review required 10 MPROVEMENTS:	Cip., Observed Survey m s and Observed Wolfice	ors (isting of
PROVEMENTS: Describe any additional IC required.	irements that may be necessary due to	ors (isting of
record review required 10 MPROVEMENTS:	irements that may be necessary due to	Stave Follers)
PROVEMENTS: Describe any additional IC required observed during the visual inspe	irements that may be necessary due to	o unique circumstances
MPROVEMENTS: Describe any additional IC required observed during the visual inspection. A) Suggest that The	irements that may be necessary due to ction: Table under Item #4	o unique circumstances
PROVEMENTS: Describe any additional IC required observed during the visual inspection of the checklists to all the checklists to al	irements that may be necessary due to ction: Table under Item #4	o unique circumstances be revised in futur TANK FARM Fence the
PROVEMENTS: Describe any additional IC required observed during the visual inspection of the checklists to all the checklists to al	irements that may be necessary due to ction: Table under Item #4 Don't hat within the parkers and No indivise	o unique circumstances be revised in Futur TANK FARM Fence th
PROVEMENTS: Describe any additional IC required observed during the visual inspection of the checklists to all the Tank Faces	irements that may be necessary due to ction: Table under Item #4 Darkers and No indivision of the protected within the protected with	o unique circumstances be revised in Futur TANK FARM Fence th
Describe any additional IC required observed during the visual inspection of the check lists to start the Tauk Form	irements that may be necessary due to ction: Table under Item #4 Table under Within the markers and was individual to protecte the "Evidence of human into	be revised in Federal TANK FARM Fence the June Site Signs becan Line only Terrory Line of Communication of the control of the
Describe any additional IC required observed during the visual inspection of the check lists to start the Tauk Form	irements that may be necessary due to ction: Table under Item #4 Darkers and No indivision of the protected within the protected with	be revised in Federal TANK FARM Fence the June Site Signs becan Line only Terrory Line of Communication of the control of the
Describe any additional IC required observed during the visual inspection of the checklists to all the Table Form sites for which the posterved laming Sign TF boorday.	irements that may be necessary due to ction: Table under Item #4 Table whithin the markers and we individe liner must be potented the "Evidence of human into a company one CP-15, CPP-	be revised in Federal TANK FARM Fence the Junion "Observed Boundary Mars SR CPP-26 which extend be
PROVEMENTS: Describe any additional IC required observed during the visual inspector of the province of the p	irements that may be necessary due to ction: Table under Item #4 Table under Within the markers and was individual to protecte the "Evidence of human into	be revised in Federal TANK FARM Fence the Junion "Observed Boundary Mars SR CPP-26 which extend be
Describe any additional IC required observed during the visual inspection of the check lists to start the Tank Form sites for which to be read to make the Tank Form Sites for which to be read to make the Tank Form Sites for which to be read to make the Tank Form Sites for which to be read to make the Tank Form Sites for which to be read to make the Tank Form Sites for which to be read to make the Tank Form Sites for which the Tank Form Sites for which the Tank Form Sites for which the tank I would be read to the tank I would be	irements that may be necessary due to ction: Table under Item #4 Table whithin the markers and we individe liner must be potented the "Evidence of human into a company one CP-15, CPP-	be revised in Futur TANK FARM Fence th Just Site Signs beca L. The only Turning Islan "Observed Boundary Mo SR CPP 26 which extend be Barriers"
Describe any additional IC required observed during the visual inspection of the Table Form of the Table II certify that the above inspection	irements that may be necessary due to ction: Table under Item #4 Table	be revised in Futur TANK FARM Fence the Junion "Observed Warning St. Starters "Observed Warning St. Barriers " St of my ability.
Describe any additional IC required observed during the visual inspection of the Table Form of the Table II certify that the above inspection	irements that may be necessary due to ction: Table under Item #4 Table	be revised in Futur TANK FARM Fence the Junion "Observed Durning St. Stor "Observed Durning St. Barriers " St of my ability.
MPROVEMENTS: Describe any additional IC required observed during the visual inspection of the property of the Tank Form Sites for which the Tank Form Sites	irements that may be necessary due to ction: Table under Item #4 Table	be revised in full that the state of the sta

Margie Enclosh	4-10-01
Inspector signature	Date
Wills M. la	4/10/01
Inspector signature	Date
Rachel & Melit	Nierio Alulia

DATE(S)/TIME((S): 4/10/01 /	/ p.m.	
INSPECTOR: _	KATHY INY Name	WAG-3 MANAGER	OSEPA Organization
INSPECTOR: _	MARGE EAGUSH Name	Title	1 Deo Organization
1. Group Numb	ber or NFA Designation:	2	
Yes	Restricted Security Acces	d limit or control public trespass: s to the INEEL s to INTEC fenced boundary	
3. Release sites	s with land use other than	Industrial: NONE	

4. Release Site IDs, descriptions, and visual inspection matrix. On the table below please indicate "YES' or "NO' for observations based upon the visual inspection. If actions have been taken associated with remediation, site changes, or changes in land-use, take photographs and fill out the "Site Inspection Photo Number Log" for the annual report. Sign location specifications are provided in the ICP. Deficiencies should be addressed in No. 8.

Release Site	Description	Evidence of Human Intrusion	Observed Boundary Monuments	Observed Warning Signs/Barriers
CPP-02	Floor Drain W of CPP-603	No- observed from BLOG exterior		Yes-signs at
CPP-41A	Fire Training Pits CPP-666 and CPP-663	NO see ikm 8	No markers absenced on north side wang	- Yes on north side
CPP-60	Paint Shop at CPP-645	NoNE	MA	sus - signs
CPP-68	Abandoned gasoline tank CPP VES-UTI-652	んっゃん	· markers on N. Corners. Pins in Sidewalk on south	Yes
CPP-80	CPP-601 Vent Tunnel drain leak	None	None	Yes
CPP-85	WCF Blower Corridor	NONE	-None - 16	sign on 3 corners
CPP-86	CPP-602 Waste Trench Sump	NONE	No markers	yes - single Sign
CPP-87	CPP-604 VOG Blower cell sump and floor drain	None	None	Yes - staisingle Sign on entry door to bldy 605
CPP-89	CPP-604/605 tunnel excavation	None	None	Yes - single sign 20 orness dear

* We were told with Cap corners were surveyed

5. Institutional Controls records review. On the table below, please indicate "YES', "NO", α"NA" for records reviewed during the inspection. Answers of "NA" indicate that the records, such as work permits or personnel training records, were not applicable at the time of the inspection (i.e., release site not accessed for work purposes).

	CFLUP	Review			Ohe	erved*	:		Observed
Release Site	Observed Surveyed Maps	Listing of Required ICs	1	ved Work (s)/RWPs	Pers Tra	onnel ining cords		erved D(s)	Notices to Affected Stakeholders
CPP-02			2	A	N/	'A	N/	'A	
CPP-41A				1		\	7	1	
CPP-60									
CPP-68									
CPP-80									
CPP-85									
CPP-86									
CPP-87									
CPP-89				1		/	,	V	

6. Provide the current status of any remedial actions at the release sites (i.e., a detailed description of the project's status based on the flowchart from Figure 3-1, Operable Unit 3-13 Group 2 Closure Evaluation Criteria and Checklist).

CALP2	this year.
Release Site	Description
CPP-02	
CPP-41A	
CPP-60	
CPP-68	
CPP-80	
CPP-85	
CPP-86	
CPP-87	
CPP-89	

No Nobs or Work Permits	Radiological Work Permits	Notices of Disturbance
		<u> </u>
correct problems:	eficiencies and what efforts or measures	NAME
8. Provide a description of any decorrect problems: SHC-11A SUCUE SUCCESS MARK SUCCESS MARK SUCCESS	EVEY PINS ARE ENLY A POINTS, SO SIGNS AND	astallod - MME 4
8. Provide a description of any decorrect problems: SHC-41A SUCULTY: SITE HIA & GB SUCULTY: MPEK SUKVEY NO THEM 5 - SIGNA	POINTS SO SIGNS AND The CFULP Commently	astallod - MME 4
8. Provide a description of any decorrect problems: SHC-41A SUCULTY: SITE HIA & GB SUCULTY: MPEK SUKVEY NO THEM 5 - SIGNA	POINTS, SO SIGNS AND The CFULP Comently le	MINISTER OF TION FIRS ARE SUFFE
8. Provide a description of any decorrect problems: SHC-11A Success SITE HIA = 68 SURVEY MARK SURVEY COURT COURT	POINTS SO SIGNS AND The CFULP Comently le	ASTABLOOD MAR Y PHYSICAL OFTION FINS ARE SUFF, palog updated we perturing to this
8. Provide a description of any decorrect problems: SHC-11A Success SITE HIA = 68 SURVEY MARK SURVEY COURT COURT	POINTS, 30 SIGNS AND The CFULP Comently I Tout Check those items	ASTA GLOOD MARE Y PHYSICAL OPTION PINS ARE SUFFE Delay a potented live Actobring to this Survey maps Li
8. Provide a description of any decorrect problems: SHC-11A Success SITE HIA = 68 SURVEY MARK SURVEY COURT COURT	POINTS, 30 SIGNS AND The CFULP Comently I Tout Check those items	ASTA GLOOD MARE Y PHYSICAL OPTION PINS ARE SUFFE Delay a potented live Actobring to this Survey maps Li
8. Provide a description of any decorrect problems: SHC-11A Success SITE HIA = 68 SURVEY MARK SURVEY COURT COURT	POINTS, 30 SIGNS AND The CFULP Comently I Tout Check those items	ASTA GLOOD MARE Y PHYSICAL OPTION PINS ARE SUFFE Delay a potented live Actobring to this Survey maps Li
8. Provide a description of any decorrect problems: SHC-11A Success SITE HIA = 68 SURVEY MARK SURVEY COURT COURT	POINTS, 30 SIGNS AND The CFULP Comently I Tout Check those items	ASTA GLOOD MARE Y PHYSICAL OPTION PINS ARE SUFFE Delay a potented live Actobring to this Survey maps Li

b Agency inspectors may assess a random sampling of this information to determine if there are any deficiencies.

IMPROVEMENTS:

	Ly Marinkists " to
The Steen for Good 2 may be	
fronther ferre and & promo	
	TISSUELLE TO THE THE TISSUELLE THE
<u> </u>	
certify that the above inspection report is true and accur	rate to the hest of my shility
certify that the above inspection report is true and accu	rate to the best of my ability.
certify that the above inspection report is true and accu	rate to the best of my ability.
certify that the above inspection report is true and accu	rate to the best of my ability. $4/10/01$
Margie English	4/10/01
Margie English	4/10/01

DATE(S)/TIME	(S): 4-10-01 p.n	<u> </u>	
NSPECTOR:	MARGLE ENGLISH	WAG-3 MANAGER	1060
	Name	Title	Organization
NSPECTOR: _	KATHY IVY	WAG-3 MANAGER	USEPA
	Name	Title	Organization
l. Group Num	ber or NFA Designation:	3	
2. Identify sec	urity restrictions that would lin	nit or control public trespass:	
	Restricted Security Access to		,
<u>45</u>	Restricted Security Access to	INTEC fenced boundary	
3. Release site	s with land use other than Indu	ıstrial: NOPE	

4. Release Site IDs, descriptions, and visual inspection matrix. On the table below please indicate "YES" or "NO" for observations based upon the visual inspection. If actions have been taken associated with remediation, site changes, or changes in land-use, take photographs and fill out the "Site Inspection Photo Number Log" for the annual report. Sign location specifications are provided in the ICP. Deficiencies should be addressed in No. 8.

Release Site	Description	Status of Remedial Action	Evidence of Human Intrusion	Observed Boundary Monuments	Observed Warning Signs/Barriers
CPP-01	Concrete settling basin E of CPP-603	Pre-Design	NOVE	Yes	Yes
CPP-03	Temporary Storage Area SE of CPP-603	Pre-Design	NONE	425	Yes
CPP-04	Contaminated Soil Area near CPP-603 Settling Tank	Pre-Design	None	Yes	4es
CPP-05	Contaminated Soil Area near CPP-603 Settling Basin	Pre-Design	3004	Shares - Survey markers south coppose	No · See item 7
CPP-08	CPP-603 basin filter line failure	Pre-Design	NONE	שליבול שו	Yes
CPP-09	Soil contamination NE corner of CPP-603 SB	Pre-Design	NovE	NE MONUMENTS	Yes
CPP-10	CPP-603 plastic pipe break	Pre-Design	None	Vas 3 Cornes	Y=5
CPP-11	CPP-603 sludge and water release	Pre-Design	NONE	Yes - SW Corner	Yes
CPP-13	Pressurization of solid storage cyclone NE of CPP-603	Pre-Design	NONE	markers bem	yes of bean
CPP-14	Old Sewer Treatment Plant W of CPP-604	Pre-Design	rone	Yes	Yes
CPP-19	CPP-603 to CPP-604 line leak	Pre-Design	None	Yes	Yes
CPP-34	Soil storage area (disposed trenches) in the northeast corner of the ICPP	Pre-Design	No	Yes	Yes

xx- No observed monuments were told that force corners have been surveyed

						_
Release Site	Description	Status of Remedial Action	Evidence of Human Intrusion	Observed Boundary Monuments	Observed Warning Signs/Barriers	
CPP-35	CPP-633 decontamination spill	Pre-Design	No , N	YES NE COME	Yes]
CPP-36	Transfer Line leak from CPP-633 to WL- 102	Pre-Design	No	NO - undermath tent structure - also painted atop oloct	Yes	
CPP-37A/B	Gravel Pits and Debris Landfill in/out of INTEC	Pre-Design	Yes #	Yes	Yes	K.i. Hid RREHIM
CPP-44	Grease Pit S of CPP-608	Pre-Design	No	Yes	405	
CPP-48	French Drain S of CPP-633	Pre-Design	NO	425	yes	
CPP-55	Mercury contamination area S of CPP-t-15	Pre-Design	No	Yes	Yes	
CPP-67	CPP Perc Ponds #1 and #2	Pre-Design	No	No.	tight - yes Locked - Garo]
CPP-91	CPP-633 blower pit drain	Pre-Design	04	Culter on	Yes]
CPP-92	Soil boxes W of CPP-1617	Pre-Design	N.	No **	Signs- yes	1
CPP-93	Simulated calcine disposal	Pre-Design	No	marke on 5	Yes	1
CPP-97	Tank Farm soil stockpiles	Pre-Design	-MO	Xes	yes - signs +	arze C
CPP-98	Tank Farm shoring boxes	Pre-Design	No	* *	signs-yes	7
CPP-99	Boxed soil	Pre-Design	No	xx	locked ferce	

Institutional Controls records review. On the table below, please indicate "YES", "NO", or "NA" Rec 4/14/61 for records reviewed during the inspection. Answers of "NA" indicate that the records, such as work permits or personnel training records, were not applicable at the time of the inspection (i.e., release site not accessed for work purposes).

		^ 7B	T	T		
ļ	CFLU	P Review		Observed		Observed
Release Site	Observed Surveyed Maps	Listing of Required ICs	Observed Work Permit(s)/RWPs	Personnel Training Records	Observed NOD(s)	Notices to Affected Stakeholders
CPP-01				See item		
CPP-03			sec i tem	1	Yes	
CPP-04						
CPP-05						
CPP-08						
CPP-09						
CPP-10						
CPP-11				1		
CPP-13						
CPP-14						
CPP-19						
CPP-34				-4		<u>L</u>

	CFLUI	P Review		Observed		Observed
Release Site	Observed Surveyed Maps	Listing of Required ICs	Observed Work Permit(s)/RWPs	Personnel Training Records	Observed NOD(s)	Notices to Affected Stakeholders
CPP-35						
CPP-36						
CPP-37A/B						
CPP-44		·				
CPP-48						
CPP-55						
CPP-67						
CPP-91						
CPP-92						
CPP-93						
CPP-97						
CPP-98		T				
CPP-99						

6. <u>Listing of Work Permits/RWPs/NODs.</u> Deficiencies should be addressed in No. 7.

Standard 1	01 Work Permits		Work Permits	Notices of Disturbance
did not Revie	es this document	spot checked work Order 3	95IL	SPOT CHECKED DØ1-Ø3
See gene	inspection	comment	regarding	NOD 8(C)
	•			

c Agency inspectors may assess a random sampling of this information to determine if there are any deficiencies.

DEFICIENCIES:

NED Signs	to indicate. Site CPP-05
Item #5	not check those items pertabling to this record.
	1c's and Observed Nortice to Stakeholderts)
escribe any add	itional IC requirements that may be necessary due to unique circumstances observed inspection:
escribe any add uring the visual	itional IC requirements that may be necessary due to unique circumstances observed
escribe any add	itional IC requirements that may be necessary due to unique circumstances observed inspection: The toward Peronit Finalization process be bed in IC Plan text Since the work
escribe any adduring the visual	itional IC requirements that may be necessary due to unique circumstances observed inspection: That war Penait finalization process be bed in 1C. Plan text Since the work two observed had no signatures all war to obtained
escribe any adduring the visual Comparison of the comparison of t	itional IC requirements that may be necessary due to unique circumstances observed inspection: That were Peroit finalization process be abed in IC Plan text Since the work to be observed had no signatures although that signatures are not obtained the downers to be finalized for extent to occur not observe Personnel Training Record for of the IC spection for Group 3 the
escribe any adduring the visual Describe According For B) Live	itional IC requirements that may be necessary due to unique circumstances observed inspection: That were Penait finalization process be about in IC Plan text. Since the work the work had no signatures all that signature are not obtained this downers to be finalized for entiring to occur and observed personned training Record for the IC inspection for Group 3 this general inspection comment:
escribe any add uring the visual describe any add or service of the control of th	itional IC requirements that may be necessary due to unique circumstances observed inspection: That work Pernit finalization process be able in IC Plan text Since the work were observed had no signatures although that signatures are not obtained this downers to be finalized for extent to occur not observe Personnel Training Record put of the IC inspection for Group 3 this general inspection comment: For the next IC in spection, we request that a
Decrei	itional IC requirements that may be necessary due to unique circumstances observed inspection: That work Perait Finalization process be bed in IC Plan text Since the work to we observed had no signatures alt was to that signature are not obtained this downers to be finalized for extently to occur not observing Personnel Training Record fort of the IC ispection for Group 3 this general inspection comment: For the next IC in spection, we request that a list of all NODs completed within the year preceeding the inspection be provided to the
escribe any adduring the visual Control B) Luc George Geor	itional IC requirements that may be necessary due to unique circumstances observed inspection: That work Pernit finalization process be able to IC Plan text Since the work were observed had no Signatures all this downers to be finalized for extent to occur and obtained this downers to be finalized for extent to occur not observed Personnel Training Record and the IC inspection for Group 3 this general inspection comment: For the next IC inspection, we request that a list of all NODs completed within the year preceding the inspection be provided to the Anexes at least 2 weeks prior to the inspect
escribe any adduring the visual Control B) Luc George Geor	itional IC requirements that may be necessary due to unique circumstances observed inspection: That work Perait Finalization process be bed in IC Plan text Since the work to we observed had no signatures alt was to that signature are not obtained this downers to be finalized for extently to occur not observing Personnel Training Record fort of the IC ispection for Group 3 this general inspection comment: For the next IC in spection, we request that a list of all NODs completed within the year preceeding the inspection be provided to the

I certify that the above inspection report is true and accurate to the best of my ability.

Inspector signature

Date

Date

Date

Date

Packel Li Calling Doe 10 4/11/0/

ECTOR: MARGIE ENGISH Name	WAG-3 MANAGER Title	Organization
		USEPA
Name	Title	Organization
Group Number or NFA Designation:	4	•
Yes Restricted Security Access t	o the INEEL	
Release Site ID and Description: CPI	P-83 Perched Water System at INTI	EC CPP 55-06
Release sites with land use other than In	dustrial: NONE	
Provide the current status of any remeditionstruction, O&M, etc:	al actions at the release sites, e.g., rer	nedial design,
	Name PECTOR: KATH TNY Name Group Number or NFA Designation: dentify security restrictions that would Les Restricted Security Access t Les Restricted Security Access t Release Site ID and Description: CPI Release sites with land use other than In	Name Title PECTOR: KATH INY WAG-3 MANAGER Name Title Group Number or NFA Designation: 4 dentify security restrictions that would limit or control public trespass: Restricted Security Access to the INEEL Restricted Security Access to INTEC fenced boundary

Well ID	Well ID Label Intact and Readable?	Locked?	Abutment Condition	Concrete Pad Condition	Surveyed Location Map Available?	Evidence of Human Intrusion (i.e., unauthorized drilling, unlocked or missing well lock)
CPP-33-1						
CPP-33-2						
CPP-33-3						
CPP-37-4						
CPP-55-06						
PW-1	·					
PW-2	Yes	Ves	good	Nahe	Yes	NONE
PW-3	Yes	Yes	good	Spad	yes	DONE
PW-4	Vac	Vac	s made	None	Vec	Nonce

respond to a deficiency identified in a previous inspection, take photographs and fill out "The Site

Inspection Photo Number Log' for the annual report.

Well ID	Well ID Label Intact and Readable?	Locked?	Abutment Condition	Concrete Pad Condition	Surveyed Location Map Available?	Evidence of Human Intrusion (i.e., unauthorized drilling, unlocked or missing well lock)
PW-5						
PW-6						
MW-1						
MW-2						
MW-3						
MW-4						
MW-5						
MW-6						
MW-7						
MW-8						·
MW-9						
MW-10						
MW-11						
MW-12						
MW-13						
MW-14	Yes	483	good	good	15-	NONE
MW-15						
MW-16						
MW-17						
MW-18						
MW-20						
USGS-50						
						
				1		
	- 	 				
		 	1		1	
		 			1	
		<u> </u>		—	 	
	 	 	 	+	 	
				+		<u> </u>
<u> </u>						
<u> </u>	+	 		+	+	+

Well ID	Well ID Label Intact and Readable?	Locked?	Abutment Condition	Concrete Pad Condition	Surveyed Location Map Available?	Evidence of Human Intrusion (i.e., unauthorized drilling, unlocked or missing well lock)
			<u> </u>			
	-		 			
	<u> </u>					
	 		-		-	
			ــــــــــــــــــــــــــــــــــــــ	1		<u> </u>
. Are any	non-CERCLA v	wells operating	g in the groundy	vater IC restri	ction area?	
YES	NO	NA				

	YES NO NA
	If YES, describe the wells and what program(s) they operate under. ** NOT FIL NON-CERCIA WELLS WERE INSPECTED BY EPR/IDEG: SEE NOTE (1) IN "IMPROVEMENTS" SECTION
: -	Does a DOE-ID Directive exist that restricts drilling into contaminated zones at OU 3-13 or the INEEL?
	YES NO
	If NO Explain: ** DOE 15 RESEARCHING CURRENT REQUIRENCES IS THAT MAY WORK IN PURCE OF A NEW DIE-ID DIRECTIVE (C.S. NEPP, NOD) AND WILL FROVIDE THO INFORMATION TO THE MENCIES FOR CONCURRENCE.
).	Have required notices been sent to affected stakeholders (if applicable)?
	YES NO NA

DEFICIENCIES:

CDD OXTENERS.	
PROVEMENTS:	
Describe any additional IC requirements that may be	necessary due to unique circumstances observed
during the visual inspection:	
PRIVA TO THE 04/10/0; FIELD) INSPECTION, THE AGENCIES S.
WITH ERIC NEHER PUNCERAING	RUSP 4 & 5 WELL PHECKLISTS.
THESE CHECKLISTS COVER 16-19P	
OR WAYSUAL CONDITIONS AT THE	WELL HEADS. EATHER THAN
BEGINNING WITH THE 2002 ICME.	IESE CHECKLISTS WILL BE INCLUBE
EZGINNING WITH THE BOOZ TEMP.	WELLS NOT POTERED BY A CHECKLE
ANTICIPATION OF THIS CHANCE IN A	PROCESS EPATIONS ONLY PERFOR
WILL BY INCLUDED AS PART OF IC ANTICIPATION OF THIS CHANGE IN A A SPOT CHECK OF A FEW SITE W I certify that the above inspection report is true and a	accurate to the best of my ability.
Toolsty that the accidentapeonical report to that the	
. 1	
11.71 m/	nul. I
11All 1/1/19	07/11/01
	D.A.
Inspector signature	Date
1 M1 / 1-1	
Marcie Enlish	4/11/01
Margie English	4/11/01